

**MPERIA® Platform Software 11.6.0**

23-September-2022

**RELEASE OVERVIEW:**

MPERIA release 11.6.0 has support for the 8" MPERIA Controller, enhancements for Axian IQ print systems, and user experience bug fixes and incremental improvements.

**RELEASE LOCATION:**[MPERIA 11.6.0 Release Download](#)**WHO SHOULD UPGRADE?**

Users of 8" MPERIA Controller

Users of Axian IQ™ Print System

**NEW BENEFITS AND FEATURES:**

- Support for new MPERIA 8" Controller
- Updated startup screen to display the MPERIA Controller serial number in the start-up logo for easier troubleshooting. This is only available for new controllers with the serial number programmed into the controller.
- Cost per Mark Estimator has added support for Axian IQ. Use the software tool in the MPERIA platform to estimate cost of a message with the Axian IQ printing system. Beneficial while designing messages to characterize the effect that messages changes will have on the ink consumption and the cost of the message.
- Dot Size adjustments can be made in the MPERIA Editor for individual Axian IQ messages. Axian IQ has a global setting for dot size and now it can be overridden for individual messages if needed. Enable this for use when customizing messages for certain substrates or package sizes, or for adjusting the cost/mark.
- Add information to the GUI for number of Axian IQ prints made by the installed Jetting Disc to enable easier troubleshooting of Jetting Discs.

**COMPATIBILITY NOTE:**

This version cannot be installed on older models of the MPERIA Lite controller with single Ethernet port. The last version with support for old MPERIA Lite controllers is 6.3.x. This version will work on second generation 7" MPERIA Lite controllers.

**KEY FIXES AND ENHANCEMENTS**

Fix has been implemented for corrupted print buffer on Axian IQ Systems where the beginning and the end of the messages are not correct.

Axian IQ Jetting Disc database updates creation time

Axian IQ PH stats added to troubleshoot backup file

MPERIA HE 15" Controller clock drift

Fix L-Series printers skip throttle mode

Warn user when database is too large for import

Fix log exports when duplicate records exist

PH status continuously updated when Axian marker is disabled